


QUICK START

SOFTER

SF500PRO | SF600PRO


SF700PRO | SF800PRO










Vydání: 6 | platnost od: 1. 6. 2025





- (CZ) Návod Quick Start nenahrazuje návod k použití!
- (GB) The Quick Start guide is not a substitute for the instruction manual!
- (D) Die Schnellstartanleitung ist kein Ersatz für die Bedienungsanleitung!
- (F) Le guide de démarrage rapide ne remplace pas le manuel d'instructions!
- (RU) Руководство по быстрому запуску не является заменой инструкции по эксплуатации!
- (PL) Podręcznik szybkiego startu nie zastępuje instrukcji obsługi!





Machine unfolding procedure – work position


1a		
1b		
2a		
2c		
2d		
3a		


2a




2b










1



h [cm / in]			
0		70 / 28	
2	▬▬	64 / 25	
4	▬▬▬▬	59 / 23	
6	▬▬▬▬▬▬	53 / 21	
8	▬▬▬▬▬▬▬▬	47 / 19	
11	TRANSPORT		




2





3



















○ 5 s














MAX 70 bar/1015 Psi






Machine folding procedure – transport position

1a		
1b		
1c		
1d		
2a		
2b		
2c		
3		

1d



2c



MAX 3 m / 9,8 ft

