


QUICK START

SOFTER


SF1050PRO | SF1250PRO









Vydání: 13 | platnost od: 1. 6. 2025




- (CZ) Návod Quick Start nenahrazuje návod k použití!
- (GB) The Quick Start guide is not a substitute for the instruction manual!
- (D) Die Schnellstartanleitung ist kein Ersatz für die Bedienungsanleitung!
- (F) Le guide de démarrage rapide ne remplace pas le manuel d'instructions!
- (RU) Руководство по быстрому запуску не является заменой инструкции по эксплуатации!
- (PL) Podręcznik szybkiego startu nie zastępuje instrukcji obsługi!





Machine unfolding procedure – work position

1a		 
1b	 	
2c		 100 bar/1450 Psi
2d		
3		
4		



2b




2c




2c









100 bar/1450 Psi




2d




← (P) →




SF1250 | 1050PRO





1



h [cm / ln]			
0		70 / 28	
2		64 / 25	
4		59 / 23	
6		53 / 21	
8		47 / 19	
11		TRANSPORT	







2





3





















○ 5 s





















MAX 70 bar/1015 Psi





Machine folding procedure – transport position

1a		
1b		
1c		  
2a		
2b		 
3		 

1c



1d



2b

