


QUICK START


SOFTER

SF500PRO | SF600PRO



SF700PRO | SF800PRO












Edition: 5 | effective from: 1. 4. 2025





- (CZ) Návod Quick Start nenahrazuje návod k použití!
- (GB) The Quick Start guide is not a substitute for the instruction manual!
- (D) Die Schnellstartanleitung ist kein Ersatz für die Bedienungsanleitung!
- (F) Le guide de démarrage rapide ne remplace pas le manuel d'instructions!
- (RU) Руководство по быстрому запуску не является заменой инструкции по эксплуатации!
- (PL) Podręcznik szybkiego startu nie zastępuje instrukcji obsługi!





Machine unfolding procedure – work position


1a		
1b		
2a		 
2c	 	   80 bar/1160 Psi
2d	 	 
3a		 


2a




2b










1



h [cm / in]			
0		70 / 28	
2		64 / 25	
4		59 / 23	
6		53 / 21	
8		47 / 19	
11	TRANSPORT		




2





3



















○ 5 s
























MAX 70 bar/1015 Psi



Machine folding procedure – transport position

1a		
1b		 
1c		 
1d		 
2a		 
2b		 
2c		 
3		

1d



2c

