




QUICK START

SOFTER








SF1050PRO | SF1250PRO




Vydání: 12 | platnost od: 1. 4. 2025





Machine unfolding procedure – work position

1a		
1b	○	
2b	○ ○	
2c	○ ○	 100 bar/1450 Psi
2d	○ ○	
3		
4		



2b




2c




2c









100 bar/1450 Psi




2d




← (P) →




SF1250 | 1050PRO





1



h [cm / ln]			
0		70 / 28	
2		64 / 25	
4		59 / 23	
6		53 / 21	
8		47 / 19	
11		TRANSPORT	




2





3





















5 s






















MAX 70 bar/1015 Psi





Machine folding procedure – transport position

1a		
1b		 
1c		 
1d		 
2a		
2b		 
3		 

1c



1d



2b

