


# QUICK START

# SOFTER

## SF500PRO | SF600PRO



## SF700PRO | SF800PRO











Vydání: 5 | platnost od: 1. 4. 2025





- (CZ) Návod Quick Start nenahrazuje návod k použití!
- (GB) The Quick Start guide is not a substitute for the instruction manual!
- (D) Die Schnellstartanleitung ist kein Ersatz für die Bedienungsanleitung!
- (F) Le guide de démarrage rapide ne remplace pas le manuel d'instructions!
- (RU) Руководство по быстрому запуску не является заменой инструкции по эксплуатации!
- (PL) Podręcznik szybkiego startu nie zastępuje instrukcji obsługi!





# Machine unfolding procedure – work position


|    |                                                                                                                                                                            |                                                                                                                                                                                               |
|----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1a |                                                                                                                                                                            |                                                                                                             |
| 1b |                                                                                           |                                                                                                             |
| 2a |                                                                                                                                                                            | <br>                      |
| 2c | <br> | <br><br>80 bar/1160 Psi |
| 2d | <br> | <br>                  |
| 3a |                                                                                                                                                                            | <br>                 |


# 2a




# 2b










1



| h [cm / in ] |           |         |  |
|--------------|-----------|---------|------------------------------------------------------------------------------------|
| 0            |           | 70 / 28 |                                                                                    |
| 2            | ▬▬        | 64 / 25 |                                                                                    |
| 4            | ▬▬▬▬      | 59 / 23 |                                                                                    |
| 6            | ▬▬▬▬▬▬    | 53 / 21 |                                                                                    |
| 8            | ▬▬▬▬▬▬▬▬  | 47 / 19 |                                                                                    |
| 11           | TRANSPORT |         |                                                                                    |




2





3



















5 s



















MAX 70 bar/1015 Psi



# Machine folding procedure – transport position

|    |                                                                                     |                                                                                      |
|----|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| 1a |                                                                                     |    |
| 1b |                                                                                     |    |
| 1c |    |    |
| 1d |   |   |
| 2a |                                                                                     |  |
| 2b |  |  |
| 2c |  |  |
| 3  |                                                                                     |  |

1d



2c

